

Traffic Incident 22SIT049880I

| | | | |
|----------------|---------------------------|--------------------|--------------------------|
| Status: | Completed | Incident Category: | 3 |
| Incident Type: | Hazard | Region: | South Coast |
| Details: | 12A - Debris - Dog Kennel | Classification: | Debris/Obstruction/Spill |

Event Metrics

| | | | |
|-------------------|----------------------|-------------------|--------------------------------|
| Start Time: | 30/11/2022 8:07PM | Initiated by: | Glenn West [STMC]* |
| Verified Time: | 30/11/2022 8:07PM | Assigned To: | Glenn West [STMC]* |
| Incident Cleared: | 30/11/2022 9:12PM | Assistance. Req.: | 30/11/2022 8:12PM |
| Normal Flow: | 30/11/2022 9:30PM | Assistance. Arr.: | 5/12/2022 2:17PM |
| End Time: | 30/11/2022 9:30PM | Police Ref. No: | 002052-30112022 RMC No:JN17021 |
| Completed By: | Grace Meaker [STMC]* | | |

Location

| | |
|-------------------|---------------------|
| Location Type: | Road |
| Road: | PACIFIC MOTORWAY |
| Direction: | Southbound |
| Suburb: | EAGLEBY |
| Road Owner: | Main Roads |
| Location Details: | Albert River Bridge |
| Primary Camera: | |

Debris / Obstruction / Spill Hazard Details

| | | | | | | | |
|--------------------|-----|--------------|------------|--------|--|---------|----|
| Debris/Vegetation: | Yes | Obstruction: | dog kennel | Spill: | | HAZMAT: | No |
|--------------------|-----|--------------|------------|--------|--|---------|----|

Network Impact

| | | | | | |
|--------------------|-----------|---------------------|-------------------|---------------------|----|
| Delay Expectation: | No Delays | Blockage Type: | Partially Blocked | No.Lanes Blocked: | 0 |
| Weather: | Fine | Lateral Position: | In Lanes | Opp. Link Affected: | No |
| | | Diversion Required: | No | Opp. Lanes Blocked: | |

Traffic Incident 22SIT049880I

Notifications

| <u>Time Occurred</u> | <u>Time Logged</u> | <u>Source/Destination</u> | <u>Direction</u> | <u>Contact</u> | <u>Contact Number</u> |
|----------------------|--------------------|---------------------------|------------------|----------------|-----------------------|
| 30/11/2022 8:06PM | 30/11/2022 8:07PM | 13 19 40 | Incoming | | |

Details: 12A - Debris - Dog Kennel

| <u>Time Occurred</u> | <u>Time Logged</u> | <u>Source/Destination</u> | <u>Direction</u> | <u>Contact</u> | <u>Contact Number</u> |
|----------------------|--------------------|---------------------------|------------------|----------------|-----------------------|
| 30/11/2022 8:09PM | 30/11/2022 8:09PM | TRU | Incoming | T10 | |

Details: ..Arrived

| <u>Time Occurred</u> | <u>Time Logged</u> | <u>Source/Destination</u> | <u>Direction</u> | <u>Contact</u> | <u>Contact Number</u> |
|----------------------|--------------------|---------------------------|------------------|----------------|-----------------------|
| 30/11/2022 8:11PM | 30/11/2022 8:11PM | EPS | Outgoing | EPS 526723 | |

Details: Publication Preview
 Phone preview: Debris on road Pacific Motorway Beenleigh, Albert River Bridge, Lane or lanes reduced, Southbound towards Stapylton, Proceed with caution.
 Twitter preview: Pacific Motorway, Beenleigh. Debris on road - Lane or lanes reduced, Southbound towards Stapylton. <https://qldtraffic.qld.gov.au/MapView.html?id=526723>
 Web preview:
 Hazard: Debris on road
 Suburbs / Localities
 Beenleigh
 Roads
 Pacific Motorway
 Description Albert River Bridge
 What to expect
 Lane or lanes reduced
 Southbound towards Stapylton
 No delays expected
 Proceed with caution
 Last updated 30 Nov 2022 08:09 pm
 Event ID
 526723
 You are about to publish changes to your event

| <u>Time Occurred</u> | <u>Time Logged</u> | <u>Source/Destination</u> | <u>Direction</u> | <u>Contact</u> | <u>Contact Number</u> |
|----------------------|--------------------|---------------------------|------------------|----------------------|-----------------------|
| 30/11/2022 8:11PM | 30/11/2022 8:11PM | STREAMS | Outgoing | Grace Meaker [STMC]* | |

Details: New Association with Operator Request:
 Start: 2022-11-30 20:10:00
 Priority: Operator Override
 Request Actions:
 PM350 SB - Albert River UC - DEBRIS AHEAD|LANES 2 AND 3||PROCEED WITH CAUTION

| <u>Time Occurred</u> | <u>Time Logged</u> | <u>Source/Destination</u> | <u>Direction</u> | <u>Contact</u> | <u>Contact Number</u> |
|----------------------|--------------------|---------------------------|------------------|----------------|-----------------------|
| 30/11/2022 8:12PM | 30/11/2022 8:12PM | Civil/Maintenance | Outgoing | Wayne RTEK | CTPI |

Details: ..Requested

| <u>Time Occurred</u> | <u>Time Logged</u> | <u>Source/Destination</u> | <u>Direction</u> | <u>Contact</u> | <u>Contact Number</u> |
|----------------------|--------------------|---------------------------|------------------|----------------|-----------------------|
| 30/11/2022 8:12PM | 30/11/2022 8:12PM | CCTV | Outgoing | #350 | |

Details: Observed On CCTV Camera in lanes 2 & 3

| <u>Time Occurred</u> | <u>Time Logged</u> | <u>Source/Destination</u> | <u>Direction</u> | <u>Contact</u> | <u>Contact Number</u> |
|----------------------|--------------------|---------------------------|------------------|----------------|-----------------------|
| 30/11/2022 8:25PM | 30/11/2022 8:25PM | Civil/Maintenance | Incoming | Stewart RTEK | |

Details: Proceeding to job

| <u>Time Occurred</u> | <u>Time Logged</u> | <u>Source/Destination</u> | <u>Direction</u> | <u>Contact</u> | <u>Contact Number</u> |
|----------------------|--------------------|---------------------------|------------------|----------------|-----------------------|
| 30/11/2022 8:31PM | 30/11/2022 8:31PM | Civil/Maintenance | Incoming | Stewart RTEK | |

Details: Arrived and spotted Dog Kennel - doing a loop around to come back for rolling block to retrieve kennel in lanes 2 & 3

| <u>Time Occurred</u> | <u>Time Logged</u> | <u>Source/Destination</u> | <u>Direction</u> | <u>Contact</u> | <u>Contact Number</u> |
|----------------------|--------------------|---------------------------|------------------|------------------------|-----------------------|
| 30/11/2022 8:47PM | 30/11/2022 8:47PM | STREAMS | Outgoing | Carmen L Fraser-Holmes | |

Traffic Incident 22SIT049880I

Details: Associated Operator Request (PM350 SB - Albert River UC - DEBRIS AHEAD|LANES 2 AND 3||PROCEED WITH CAUTION) has been removed from the device(s).

| <u>Time Occurred</u> | <u>Time Logged</u> | <u>Source/Destination</u> | <u>Direction</u> | <u>Contact</u> | <u>Contact Number</u> |
|----------------------|--------------------|---------------------------|------------------|----------------|-----------------------|
| 30/11/2022 8:51PM | 30/11/2022 8:52PM | Civil/Maintenance | Incoming | Stuart - RTEK | |

Details: ..RMC Starting Rolling Blockade

| <u>Time Occurred</u> | <u>Time Logged</u> | <u>Source/Destination</u> | <u>Direction</u> | <u>Contact</u> | <u>Contact Number</u> |
|----------------------|--------------------|---------------------------|------------------|---------------------------------------|-----------------------|
| 30/11/2022 8:55PM | 30/11/2022 8:55PM | TRU | Incoming | T10 <input type="text" value="CTPI"/> | |

Details: Advised rolling blockade complete and dog kennel retrieved - requested QPS for multi vehicle crash due to debris on road

| <u>Time Occurred</u> | <u>Time Logged</u> | <u>Source/Destination</u> | <u>Direction</u> | <u>Contact</u> | <u>Contact Number</u> |
|----------------------|--------------------|---------------------------|------------------|----------------|-----------------------|
| 30/11/2022 9:03PM | 30/11/2022 9:03PM | TRU | Incoming | T10 | |

Details: Advised Dog Kennel Retrieved

| <u>Time Occurred</u> | <u>Time Logged</u> | <u>Source/Destination</u> | <u>Direction</u> | <u>Contact</u> | <u>Contact Number</u> |
|----------------------|--------------------|---------------------------|------------------|----------------|-----------------------|
| 30/11/2022 9:12PM | 30/11/2022 9:30PM | Civil/Maintenance | Incoming | Stewart RTEK | |

Details: ..Departed

| <u>Time Occurred</u> | <u>Time Logged</u> | <u>Source/Destination</u> | <u>Direction</u> | <u>Contact</u> | <u>Contact Number</u> |
|----------------------|--------------------|---------------------------|------------------|----------------|-----------------------|
| 30/11/2022 9:37PM | 30/11/2022 9:37PM | EPS | Outgoing | EPS 526723 | |

Details: Archived

| <u>Time Occurred</u> | <u>Time Logged</u> | <u>Source/Destination</u> | <u>Direction</u> | <u>Contact</u> | <u>Contact Number</u> |
|----------------------|--------------------|---------------------------|------------------|----------------|-----------------------|
| 30/11/2022 9:38PM | 30/11/2022 9:38PM | TMC | Outgoing | | |

Details: Review Completed SIMS jobs

| <u>Time Occurred</u> | <u>Time Logged</u> | <u>Source/Destination</u> | <u>Direction</u> | <u>Contact</u> | <u>Contact Number</u> |
|----------------------|--------------------|---------------------------|------------------|-----------------------------------|-----------------------------------|
| 1/12/2022 4:31PM | 1/12/2022 4:31PM | 13 19 40 | Incoming | <input type="text" value="CTPI"/> | <input type="text" value="CTPI"/> |

Details: Owner of dog kennel called to give contact details incase of a claim:

Linked Incident/Faults

| <u>Identifier</u> | <u>Type</u> | <u>Time Logged</u> | <u>Details</u> |
|-------------------|-------------|----------------------|--|
| 22SIT049882I | Crash | 30/11/2022 8:43:26PM | 12A - Multi Vehicle Crash - 3 x vehicles |



T&IM - TRO - Incident Report

TRO_INC_002668 / TRU 09 / / 30
Nov 2022 / 49880

Complete

Score

49.15%

Incident Report Number

TRO_INC_002668

Conducted on

30/11/2022 20:08 AEST

Completed by

Fleet ID

TRU 09

SIMS Reference Number

49880

Location

Pacific Motorway
Eagleby QLD 4207
Australia
(-27.724748179178395,
153.21988677559148)

Released under RTI - DTMR

Risk Assessment

49.06%

Risk Assessment

49.06%

| | |
|------------------------------------|---|
| Weather Conditions | Drizzle / Light Rain |
| Visibility | Greater than 300m |
| Actual speed | 80km/h or greater |
| Potential Speed | 80km/h or greater |
| Vehicle Position | Shoulder/Chevrons or Median More than 0.5m from moving Traffic |
| Traffic Obstacles | Within 300m of merging or Exiting Traffic or Other Driver Obstacle |
| Congestion | No Congestion |
| Select the Overall Risk calculated | Score 201 to 325 = Medium Risk |
| Complete All Medium Risk Controls | ACTION: Undertake the job, adopting TRUMM positioning BACK UP: Consider additional TRU Type 1 or support vehicle COMMUNICATION: Consider back-up request |

If Required, Please Add Comments

Roadtek or QPS requested to attend

Incident Details

Dates and Times

| | |
|---------------------|-----------------------|
| TMC Requested | No |
| TRU Detected | Yes |
| TRU Detected Time | 30/11/2022 20:10 AEST |
| Site Arrival Time | 30/11/2022 20:11 AEST |
| Site Departure Time | 30/11/2022 20:53 AEST |

Address

Location of Incident

Pacific Motorway

Eagleby QLD 4207
Australia
(-27.724622301783157,
153.21975993938113)

Secondary Reference

Southbound Albert River
Bridge

Details

TIMS Area Group

South Coast

Select TIMS Area

6 - South Coast, Pacific Motorway
from Exit 30 to Exit 62

Asset Owner

Department of Transport and
Main Roads

Agencies On-site

Yes

Type of Agency

Roadtek

Description

Description

Primary Incident

Spills / Hazmat / Debris

Secondary Incident

Spills / Hazmat / Debris

Direction

South

Affected Lanes

Lane 2

Lane 3

Posted Speed Limit

110km/h

Assets

Assets Damaged

No

Casualties

Casualty Severity

Nil Injury

Conditions

| | |
|-------------------------------|--|
| Road Conditions | Bridge Highway/Motorway Wet / Slippery |
| Road Surface | Sealed - Wet |
| Atmospheric Conditions | Light Rain Overcast |
| Light Conditions | Darkness |
| Type | Unlighted |

Actions

Actions

Action taken

Minor Incident Response

Further details of incident specifics and actions taken

Tru detect debris on dividing line of lanes 2 and 3 observed a large dog kennel
 Tru returned and stopped in shoulder to provide pre warning of hazardous debris in lanes
 TMC updated and Roadtek or QPS requested to attend urgently
 Roadtek attended and removed debris

Limited photos obtained due to distance between tru and debris and atmospheric conditions.



Photo 1

DCA Code

999 - Non-Crash

TCP

TCP

1 - Shoulder

TCP Comments

No cones deployed, VMS displaying messages "Reduce speed" and "Debris in lane"

Variation to TCP

Was a variation to TCP required by an authorising officer?

Yes

TCP Authorising Officer Name

CTPI

Badge Number

Nil

Station

TMC

Logistics

Bags of Chemsorb

Fuel Added

Debris Collected

RACQ Clearance Tow

VRO Name

VRO Unit ID

Additional Comments

Any comments

Nil

Were all Safety Processes followed?

Yes



Photo 1

Traffic Incident 22SIT049882I

| | | | |
|----------------|--|--------------------|---------------|
| Status: | Completed | Incident Category: | 2 |
| Incident Type: | Crash | Region: | South Coast |
| Details: | 12A - Multi Vehicle Crash - 3 x vehicles | Classification: | Primary Crash |

Event Metrics

| | | | |
|-------------------|----------------------|-------------------|-------------------------------|
| Start Time: | 30/11/2022 8:40PM | Initiated by: | Carmen L Fraser-Holmes[STMC]* |
| Verified Time: | 30/11/2022 8:41PM | Assigned To: | Carmen L Fraser-Holmes[STMC]* |
| Incident Cleared: | 30/11/2022 9:15PM | Assistance. Req.: | |
| Normal Flow: | 30/11/2022 9:15PM | Assistance. Arr.: | |
| End Time: | 30/11/2022 9:25PM | Police Ref. No: | |
| Completed By: | Grace Meaker [STMC]* | | |

Location

| | |
|-------------------|---------------------|
| Location Type: | Road |
| Road: | PACIFIC MOTORWAY |
| Direction: | Southbound |
| Suburb: | YATALA |
| Road Owner: | Main Roads |
| Location Details: | After Exit 35 |
| Primary Camera: | UC with Mi-Electric |

Crash Details

Collision With/Involving: Road Infrastructure: No Vegetation: No Pedestrian: No Cyclist: No Animal: None

Resulting In: QAS Attended: Yes QFRS Attended: No FCU Attended: No Hazmat: No QPS Attended: No Spill:

No. Vehicles Involved: 2 No. People injured: 1 No. of Fatalities: 0 Armis DCA Code:

Vehicles Involved

| VehicleType | TowingRequired | Carriageway | Rolled Over | Reg. No | State | Manufacturer | Colour |
|-------------|----------------|----------------|-------------|---------|-------|--------------|--------|
| | | On Carriageway | No | NR | Qld | PEUGEOT | Green |
| | | On Carriageway | No | | Qld | | |

Network Impact

| | | | | | |
|--------------------|---------|---------------------|-------------------|---------------------|----|
| Delay Expectation: | Delays | Blockage Type: | Partially Blocked | No. Lanes Blocked: | 2 |
| Weather: | Showers | Lateral Position: | In Lanes | Opp. Link Affected: | No |
| | | Diversion Required: | No | Opp. Lanes Blocked: | |



Traffic Incident 22SIT049882I

Notifications

| <u>Time Occurred</u> | <u>Time Logged</u> | <u>Source/Destination</u> | <u>Direction</u> | <u>Contact</u> | <u>Contact Number</u> |
|----------------------|--------------------|---------------------------|------------------|----------------|-----------------------|
| 30/11/2022 8:44PM | 30/11/2022 8:44PM | TRU | Incoming | T10 CTPI | |

Details: Multi Vehicle Crash - swerved to miss debris

| <u>Time Occurred</u> | <u>Time Logged</u> | <u>Source/Destination</u> | <u>Direction</u> | <u>Contact</u> | <u>Contact Number</u> |
|----------------------|--------------------|---------------------------|------------------|------------------------|-----------------------|
| 30/11/2022 8:47PM | 30/11/2022 8:47PM | STREAMS | Outgoing | Carmen L Fraser-Holmes | |

Details: New Association with Operator Request:
 Start: 2022-11-30 20:46:00
 Priority: Operator Override
 Request Actions:
 PM350 SB - Albert River UC - MULTI VEHICLE CRASH AHEAD||PROCEED WITH CAUTION

| <u>Time Occurred</u> | <u>Time Logged</u> | <u>Source/Destination</u> | <u>Direction</u> | <u>Contact</u> | <u>Contact Number</u> |
|----------------------|--------------------|---------------------------|------------------|----------------|-----------------------|
| 30/11/2022 8:50PM | 30/11/2022 8:50PM | CCTV | Outgoing | #350 | |

Details: Observed On CCTV Camera

| <u>Time Occurred</u> | <u>Time Logged</u> | <u>Source/Destination</u> | <u>Direction</u> | <u>Contact</u> | <u>Contact Number</u> |
|----------------------|--------------------|---------------------------|------------------|----------------|-----------------------|
| 30/11/2022 8:54PM | 30/11/2022 8:54PM | EPS | Outgoing | EPS 526730 | |

Details: Publication Preview
 Phone preview: Multi-vehicle Crash Pacific Motorway Beenleigh, After Exit 35, Lane or lanes reduced, Southbound towards Yatala, Proceed with caution.
 Twitter preview: Pacific Motorway, Beenleigh. Multi-vehicle Crash - Lane or lanes reduced, Southbound towards Yatala. <https://qldtraffic.qld.gov.au/MapView.html?id=526730>
 Web preview:
 Multi-vehicle Crash
 Suburbs / Localities
 Beenleigh
 Roads
 Pacific Motorway
 Description After Exit 35
 What to expect
 Lane or lanes reduced
 Southbound towards Yatala
 Proceed with caution
 Last updated 30 Nov 2022 08:44 pm
 Event ID
 526730

| <u>Time Occurred</u> | <u>Time Logged</u> | <u>Source/Destination</u> | <u>Direction</u> | <u>Contact</u> | <u>Contact Number</u> |
|----------------------|--------------------|---------------------------|------------------|-----------------|-----------------------|
| 30/11/2022 9:01PM | 30/11/2022 9:01PM | QPS | Outgoing | Georgia - DTACC | |

Details: QPS Requested

| <u>Time Occurred</u> | <u>Time Logged</u> | <u>Source/Destination</u> | <u>Direction</u> | <u>Contact</u> | <u>Contact Number</u> |
|----------------------|--------------------|---------------------------|------------------|----------------|-----------------------|
| 30/11/2022 9:06PM | 30/11/2022 9:06PM | TRU | Incoming | T10 | |

Details: Advised MoP has moved injured women to left shoulder - waiting on QAS to arrive

| <u>Time Occurred</u> | <u>Time Logged</u> | <u>Source/Destination</u> | <u>Direction</u> | <u>Contact</u> | <u>Contact Number</u> |
|----------------------|--------------------|---------------------------|------------------|----------------|-----------------------|
| 30/11/2022 9:08PM | 30/11/2022 9:08PM | TRU | Incoming | T10 | |

Details: Advised debris has been removed now managing mult vehicle due to debris

| <u>Time Occurred</u> | <u>Time Logged</u> | <u>Source/Destination</u> | <u>Direction</u> | <u>Contact</u> | <u>Contact Number</u> |
|----------------------|--------------------|---------------------------|------------------|-------------------------|-----------------------|
| 30/11/2022 9:11PM | 30/11/2022 9:11PM | QPS | Outgoing | Georgia DTACC / Debra F | |

Details: Called DTACC at 8:50 hrs - Georgia advised to call Police Link as they needed a job number. I called police link and spent 15 minutes on the phone trying to organise a crew to attend. In that time it had cleared off to the side but they were still sending a crew

| <u>Time Occurred</u> | <u>Time Logged</u> | <u>Source/Destination</u> | <u>Direction</u> | <u>Contact</u> | <u>Contact Number</u> |
|----------------------|--------------------|---------------------------|------------------|----------------|-----------------------|
| 30/11/2022 9:13PM | 30/11/2022 9:15PM | TRU | Incoming | T10 | |

Details: Advised RTEK departed and QAS have departed from scene transported 1 x Driver with minor injuries

Traffic Incident 22SIT049882I

| <u>Time Occurred</u> | <u>Time Logged</u> | <u>Source/Destination</u> | <u>Direction</u> | <u>Contact</u> | <u>Contact Number</u> |
|----------------------|--------------------|---------------------------|------------------|----------------|-----------------------|
| 30/11/2022 9:13PM | 30/11/2022 9:13PM | QPS | Outgoing | Mick DTACC | |

Details: Stood down as job cleared

| <u>Time Occurred</u> | <u>Time Logged</u> | <u>Source/Destination</u> | <u>Direction</u> | <u>Contact</u> | <u>Contact Number</u> |
|----------------------|--------------------|---------------------------|------------------|----------------------|-----------------------|
| 30/11/2022 9:14PM | 30/11/2022 9:14PM | STREAMS | Outgoing | Grace Meaker [STMC]* | |

Details: Associated Operator Request (PM350 SB - Albert River UC - MULTI VEHICLE CRASH AHEAD) PROCEED WITH CAUTION) has been removed from the device(s).

| <u>Time Occurred</u> | <u>Time Logged</u> | <u>Source/Destination</u> | <u>Direction</u> | <u>Contact</u> | <u>Contact Number</u> |
|----------------------|--------------------|---------------------------|------------------|----------------|-----------------------|
| 30/11/2022 9:16PM | 30/11/2022 9:16PM | TRU | Outgoing | T10 | |

Details: ..Departed advised nil infrastructure damage

| <u>Time Occurred</u> | <u>Time Logged</u> | <u>Source/Destination</u> | <u>Direction</u> | <u>Contact</u> | <u>Contact Number</u> |
|----------------------|--------------------|---------------------------|------------------|----------------|-----------------------|
| 30/11/2022 9:24PM | 30/11/2022 9:24PM | TMC | Outgoing | 1st and Final | |

Details: STMC SCR Incident Notification (No.1 and Final).
 Location: Pacific Motorway, Southbound, Albert River Bridge, Yatala.
 Time Incident Occurred: 20:40 hrs.
 Incident Type: Multi Vehicle Crash, 2x Cars, Lanes 3 and 4 were blocked. 1x minor injury transported by QAS.
 Impact: 1.5 km of congestion cleared.
 Time Incident Cleared: 21:15 hrs.
 Action: STMC Managed. QLD Traffic, 131940, VMS Albert River, Nil infrastructure damage.
 Groups Attended: QAS, TRU, RMC and Tow.
 Likely Media Coverage: Local and Social Media.

| <u>Time Occurred</u> | <u>Time Logged</u> | <u>Source/Destination</u> | <u>Direction</u> | <u>Contact</u> | <u>Contact Number</u> |
|----------------------|--------------------|---------------------------|------------------|----------------|-----------------------|
| 30/11/2022 9:24PM | 30/11/2022 9:24PM | EPS | Outgoing | EPS 526730 | |

Details: Archived

| <u>Time Occurred</u> | <u>Time Logged</u> | <u>Source/Destination</u> | <u>Direction</u> | <u>Contact</u> | <u>Contact Number</u> |
|----------------------|--------------------|---------------------------|------------------|----------------|-----------------------|
| 30/11/2022 9:43PM | 30/11/2022 9:43PM | TMC | Outgoing | | |

Details: Review Completed SIMS jobs

Linked Incident/Faults

| <u>Identifier</u> | <u>Type</u> | <u>Time Logged</u> | <u>Details</u> |
|-------------------|-------------|----------------------|---------------------------|
| 22SIT049880I | Hazard | 30/11/2022 8:07:49PM | 12A - Debris - Dog Kennel |

Released under RTI/DTMR





T&IM - TRO - Incident Report

TRO_INC_002728 / TRU 09 / / 30
Nov 2022 / 49882

Complete

Score

47.27%

Incident Report Number

TRO_INC_002728

Conducted on

30/11/2022 20:47 AEST

Completed by

Fleet ID

TRU 09

SIMS Reference Number

49882

Location

Pacific Motorway
Eagleby QLD 4207
Australia
(-27.72608013717782,
153.22107163982952)

Released under RTI - DTMR

Risk Assessment

47.17%

Risk Assessment

47.17%

| | |
|------------------------------------|--|
| Weather Conditions | Drizzle / Light Rain |
| Visibility | Greater than 300m |
| Actual speed | 40km/h or less |
| Potential Speed | 80km/h or greater |
| Vehicle Position | Impeding Traffic |
| Traffic Obstacles | No Driver Obstacles or Distractions |
| Congestion | Major |
| Select the Overall Risk calculated | Score 201 to 325 = Medium Risk |
| Complete All Medium Risk Controls | ACTION: Undertake the job, adopting TRUMM positioning BACK UP: Consider additional TRU Type 1 or support vehicle COMMUNICATION: Consider back-up request |

If Required, Please Add Comments

Roadtek on scene with entire road closure

Incident Details

Dates and Times

| | |
|---------------------|-----------------------|
| TMC Requested | No |
| TRU Detected | Yes |
| TRU Detected Time | 30/11/2022 20:47 AEST |
| Site Arrival Time | 30/11/2022 20:48 AEST |
| Site Departure Time | 30/11/2022 21:12 AEST |

Address

Location of Incident

Pacific Motorway
Stapylton QLD 4207
Australia

Secondary Reference

Southbound between exits 35
and 38

Details

TIMS Area Group

South Coast

Select TIMS Area

6 - South Coast, Pacific Motorway
from Exit 30 to Exit 62

Asset Owner

Department of Transport and
Main Roads

Agencies On-site

Yes

Type of Agency

Queensland Ambulance Service

Roadtek

Towing Company

Description

Description

Primary Incident

Crash

Secondary Incident

Crash

Direction

South

Affected Lanes

Lane 3

Lane 4

Posted Speed Limit

110km/h

Assets

Assets Damaged

No

Casualties

Casualty Severity

Transport Casualty - Minor

Number of Transport Casualty - Minor

1

Conditions

| | |
|-------------------------------|---|
| Road Conditions | Bridge Highway/Motorway Temporary Object on Carriageway Wet / Slippery |
| Road Surface | Sealed - Wet |
| Atmospheric Conditions | Light Rain Overcast |
| Light Conditions | Darkness |
| Type | Unlighted |

Vehicle(s)

Vehicle

Vehicle 1

Vehicle Type

Car

Registration Number

NR



Photo 1

Make

Other

Model

Peugeot 307

Body

Hatchback

Colour

Green

Actions

Actions

Action taken

Minor Incident Response

Further details of incident specifics and actions taken

Tru detect crash at location due to debris in lane.
TMC updated single vehicle crash minor injury, no infrastructure damage, 1 vehicle towed, 1 person transported by QAS
Roadtek on scene for previous incident and complete closure in place.
Vehicle uplifted and all clear from scene



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7

DCA Code

307 - Vehicle Movements not Known

TCP

TCP

8 - Full Closure

TCP Comments

Roadtek conducted full closure

Variation to TCP

Was a variation to TCP required by an authorising officer?

No

Logistics

Bags of Chemsorb

Fuel Added

Debris Collected

RACQ Clearance Tow

VRO Name

VRO Unit ID

Additional Comments

Any comments

Nil

Were all Safety Processes followed?

Yes

Released under RTI - DTMR

Appendix



Photo 1



Photo 2

Released under RTI - DTMR



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7